Oil Field Environmental Incident Summary

Responsible Party: HUNT OIL COMPANY
Well Operator: HUNT OIL COMPANY
Well Name: ALEXANDRIA 161-100-22-15H-1

Field Name: ALEXANDRIA Well File #: 28501

Date Incident:8/9/2014Time Incident:13:40Facility ID Number:County:DIVIDETwp:161Rng:100Sec:22Qtr:

Location Description:

Submitted By: MARTIN MAKHANU Received By:

Contact Person: MARTIN MAKHANU

1900 NORTH AKARD STREET DALLAS, TX 75201-2300

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.3 Mile

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine

Other 60 Barrels 57 Barrels 60 barrels

Description of Other Released Contaminant:

OIL BASED DRILLING MUD

Inspected: Written Report Received: 9/10/2014 Clean Up Concluded: 8/21/2014

Risk Evaluation:

NONE

Areal Extent:

Potential Environmental Impacts:

NONE

Action Taken or Planned:

SPILL CONTAINED BY CONTAINMENT PLASTIC AND THE LOCATION BERM. PUMP WAS SHUT DOWN. VALVE WAS CLOSED. VACUUMED UP SPILL. CONTAMINATED SOIL WAS SCRAPED UP AND HAULED TO A STATE APPROVED DISPOSAL FACILITY. DISCUSSED INCIDENT AND THE IMPORTANCE OF DOUBLE CHECKING VALVE AND LINES ALIGNMENTS BEFORE FLUID TRANSFER.

Wastes Disposal Location: INDIAN HILLS SOLIDS MANAGEMENT DISPOSAL

14070 43RD ST NW ALEXANDER, ND 58831

Agencies Involved: AREA NDIC FIELD INSPECTOR MARC BINNS

Updates

Date: 8/13/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location during drilling activities according to the report. NDIC retains oversight.